

Customer Service Notice

Product:

cPB-4612, cRT-4612HD (PCB Rev. 1.0)

Errata:

When using a cPB-4612 with a cRT-4612 HD (PCB Rev1.0), depending upon IDE configuration, the customer may notice a 30 second delay, at boot, due to drive identification.

Severity:

This anomaly is most prevalent when both primary and secondary devices are present.

Workaround:

None.

Solution:

Future board revisions of the cRT-4612HD will incorporate a fix.