

## Customer Service Notice

**Product:**

**Date: 8/15/05**

CPB4612 cPCI Integrated Board Computer (any speed)

### Errata:

The CPB4612 has console redirection disabled by default. Some customers may order a CPB4612 only with no rear transition module (RTM). The video connection for the CPB4612 is routed to the CRT4612 or CRT4612HD RTM. If no video is available, console redirection cannot be enabled.

### Severity:

Minor

### Workaround:

Connect video to the RTM and enable console redirection.

### Solution:

There is no solution planned.