

## Customer Service Notice

**Product:** PICMG 1.0 Products      **Date:** October 16, 2007

**Errata:**

Some customers require hardware monitoring software for DTI's PICMG 1.0 CPU boards, i.e. the LBC9017, LBC9116, LBC9216, LBC9326, and LBC9426. DTI does not provide this hardware monitoring software or an API for customer's to use.

**Severity:**

N/A

**Workaround:**

N/A

**Solution:**

There is a freeware application that will take advantage of the hardware monitor on these boards (ADM1026) and provide the current status of the voltages, CPU fan speeds, and temperatures of the board. This freeware is called Speedfan and can be downloaded at <http://www.almico.com/speedfan.php>

This product has not been completely validated by DTI. Therefore, the product is not officially supported by DTI and problems with the software can't be addressed by DTI.